

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12143

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080074-2

RECEIVED FROM

DATE REC'D. 5-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.	S.O. NO.
	DRAWING NO. AND DESCRIPTION										
2	322	000000	179	0	10						
	731250 Drive Assembly										
											QUANTITY ACCEPTED REJECTED REMARKS Not to M.I. 4507 HOLD INET 15.0 CONDUCT FOR

RECEIVED
BY

INSPECTED

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 12165

2941 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 5-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHANGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R	ACCT. OR W.O. NO.	S.O. NO.
	DRAWING NO. AND DESCRIPTION										
6	322	000000	201	0	15						
	731154 2 Shaft Assy Dr. Motor										
	IPB 7-61										QUANTITY ACCEPTED REJECTED REMARKS All done

RECEIVED
BYINSPECTED
BY

DATE

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080074-2